


CORNER RECORDDocument Number CR1259City of OAKLANDCounty of Alameda, CaliforniaBrief Legal Description PARCEL A OF P.M. 1562 (BK 84 Pg. 76)**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 8/20/99

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner – Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found standard monument (Per B.M. 76)

Found 5/8" rebar & plastic cap R.C.E. 18650 (Per CR 323)

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar & plastic cap L.S. 4961

Set nail & tag L.S. 4961

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Robert J. Brunel 10-14-99.

Signed _____ P.L.S. or R.C.E. No. 4961

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9-8-99

and examined and filed 10-29-99

Signed Russell R. Penland, Jr. P.L.S. or R.C.E. No. 5726

Title Deputy County Surveyor

County Surveyor's Comment _____

