


CORNER RECORD

BK 55 PG 62

APN No. _____ (Optional) Document Number CR 3737
 Unincorporated LIVERMORE County of ALAMEDA, California
 Brief Legal Description STA. 184+98.26 N. LIVERMORE AVE.



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☒
 Date of Survey JUNE 15, 2009

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD 83 Epoch _____
 Elev. _____

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to
 ESTABLISH X / REESTABLISH _____ the position of an existing monument PRIOR X / SUBSEQUENT _____
 to street or highway reconstruction. (Use this portion only when applicable.)

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND BROKEN OFF IRON BOLT ON N. LIVERMORE AVE. @
STATION 184+98.26, NO R.P.'S SET,
MONUMENT ID# XV1524

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on AUGUST 20, 20 09.

Signed Robert A. Machado L.S. or R.C.E. Number 7380



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 20, 20 09 and examined
 and filed 11-14-2013.

Signed [Signature] Title County Surveyor



County Surveyor's Comment _____

XV1524



N.T.S.

N. Livermore Av.

Station 184+98.26 Iron Bolt, Found Broken Off, Mon ID XV15Z4